



Technical Support Bulletin (Last update 6-13-6)

## Drawing Pen Plot Before Cutting Rubber

Abstract: Sometimes it is hard to see where the knife cuts on rubber to weed it correctly. This option allows drawing on the rubber prior to cutting the rubber.

In printer driver properties set the following:

- Rubber mode (pen then knife) = yes

- Click on + in front of rubber mode

  - Change force for pen 15-20%

  - Change Speed for pen 10-30%

- Click on + on send force to tool: set force for pen 1 for rubber cutting (35-60%)

- Click on + on send speed to tool: set speed for rubber cutting to 10%

- Select yes for send force to tool and send speed to tool.

In remote panel

- setup -> settings

- change cad override = off

- click save setup

Copyright 2006 Allen Datagraph Systems – All Rights Reserved